


Części niezbędne do skonstruowania oprawy na bazie profilu PAC-ALU



Profil (A)



Zaślepki (B)



Osłona (C)



Taśma LED (D)


Elementy niezbędne przy czynnościach montażowych:

- klej montażowy


UWAGA! Wszystkie taśmy LED powinny być podłączone do zasilacza 12 V lub 24 V.


WAŻNE: Instrukcja przedstawia najbardziej podstawową formę montażu.
Więcej metod i powiązanych akcesoriów znajdziesz na stronie

1. Wklej taśmę LED (E), załóż osłonkę (D), a następnie załóż zaślepkę (C). Wyprowadź kabel zasilający.



2. Nanieś klej na powierzchnie montażową. Podłącz zasilanie i umieść profil na miejscu.





Parts needed to mount the PAC-ALU extrusion



Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)


Tools needed for mounting:

- mounting glue

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found

1. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Feed the power cable.



2. Apply glue to the mounting surface. Connect power and mount the extrusion.

